



ROGER L. BLAKE, EXECUTIVE DIRECTOR

CALIFORNIA INTERSCHOLASTIC FEDERATION

CIF STATE OFFICE • 4658 DUCKHORN DRIVE • SACRAMENTO, CA 95834 • PH: 916-239-4477 • FX: 916-239-4478 • WWW.CIFSTATE.ORG

Baseball Bat Decertification List

Updated August 14, 2012

Please check back as the CIF will keep this list updated. Cut and past the following link into your web browser: http://www.cifstate.org/images/PDF/NHFS_Rule_Changes/Baseball_Bat_Decertification_List_-_2012.pdf

The NFHS has been informed by the NCAA that the BBCOR decertification process has been implemented for the following baseball bats. Effective immediately and until further notice, the bats listed below should be considered a non-compliant bat and subject to NFHS Baseball Rules 4-1-3b and 7-4-1a. ***Most recently added bad to the decertification list is listed first**

- Reebok Vector TLS 32-inch model (added 8/14/12)



- Reebok Vector TLS 33-inch model (added 3/26/12)



- Marucci CAT5 33-inch model (added 2/21/12)

